



# **Technical Service BULLETIN**

December 7, 2001

Title:

## **ACCESSORY DRIVE BELT/ BELT TENSIONER ASSEMBLY NOISE**

Models:

'00 - '01 Celica & MR2 Spyder

ENGINE  
EG014-01

**Introduction** Some 1ZZ-FE and 2ZZ-GE engines may exhibit squealing and/or rattling noises emanating from the engine compartment during vehicle operation, especially during deceleration at slow speeds after cold soak. The Accessory Drive Belt and Belt Tensioner have been improved to correct this condition.

**Applicable Vehicles**

- 2000 - 2001 model year Celica GT/GTS and MR2 Spyder vehicles produced BEFORE the Production Change Effective VINs listed below.

### **Production Change Information**

MODEL	PRODUCTION CHANGE EFFECTIVE VIN
Celica GT	JTDDR32T#10106005
Celica GTS	JTDDY38T#10049473
MR2 Spyder	JTDFR320#10039271

### **Parts Information**

VEHICLE	PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME
Celica GT w/ AC	90916-02432	90916-02534	Accessory Drive Belt
Celica GT w/o AC	90916-02468	90916-02535	
Celica GTS	90916-02310	90916-02540	
MR2 Spyder	90916-02486	90916-02537	
Celica GT Celica GTS MR2 Spyder	16601-22010	16601-22011	Belt Tensioner Sub-Assembly (Hydraulic Cylinder)
	N/A	90105-08415	Bolt, Flange
Celica GT MR2 Spyder	16620-22010	16620-22011	Belt Tensioner Assembly, Complete
Celica GTS	16620-22030	16620-22031	Belt Tensioner Assembly, Complete

### **Warranty Information**

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
EG8001	R & R Accessory Belt Tensioner	0.6	16620-22010	91	99

Applicable Warranty\*:

This repair is covered under the Toyota Comprehensive Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

\* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



Toyota Supports ASE Certification

Page 1 of 2